Work Order ID 103086

Quality Control

D 3443-041 B 103086

\*103086\*

Page 1

June-12-13 9:26:44 AM Item ID: D3443-041 Accept Setup Start \*N900040100\* Revision ID: Strut Weldment Assembly Item Name: \*4\* Start Oty: 4.00 **Start Date:** 6/11/13 **Cust Item ID:** Required Date: 6/11/13 Req'd Qty: 4.00 **Customer:** Reference: Run Process Plan: \_\_M\_\_\_\_ Date: 13-06-17 Tooling: Date: **Approvals:** Stop Date: SPC (Y/N): Date: Tool # Plan Operation Tool ID Sequence ID/ Set Up/ Accept Reject Reject Insp. Work Center ID Qty Description Code **Qty** Number Stamp **Run Hours** Draw Nbr **Revision Nbr** D3443 Rev C 100 0.00 Large Fab \*100\* Large Fab 0.00 Memo Weld assembly as per dwg D3443 Large Fab M120854 QC9- Inspect visual per QSI004- Fusion Welds 0.00 110 DAS \*110\* 9 1401.93 QC 0.00 Memo Quality Control DAS QC5- Inspect part completeness to step on W/O 0.00 120 9 \*120\* 66-10-11 QC 0.00 Memo

DQA: Date:						WORK ORDER NON-CONFORMANCE / UPDATE								
QA Closed:			Date:			WORK ORDER NON-	-CC	ONFO	RMANCE / UPDA	ATE SA	ork Order up	date only	AEROSPACE	
	-	<del></del>				DISPOSITION				AGAINST DE		i		
Work Orde	er:					DISPOSITION								
						Rework			<b>├</b> ──	rosstube		Water Jet	Engineering	
Part N	۰۰. <u> </u>					Scrap			<b>У</b> —	Small Fab		d. Eng. Coor.	Quality	
						Use-as-is		Therr	~ <del></del>	Finishing	Rec/Stor	e/Packaging	Other	
NCR N	No					Suspected Unapproved			Large Fab Co	omposite		Supplier		
Root					Desci	ription of work order update	1	nitial	Action		Sign &			
Cause		Date	Step	Qty		or non-conformance	Ch	ief Eng	Description	on	Date	Verification	QC Inspector	
Design														
Doc/Data														
Equip/Tooling	Щ													
Handling/Pre	Ш													
Material	Ш													
Operator	Ш													
Offset/Setup														
Process											i			
Supplier														
Training	Ш													
Transport	Ш									•				
Unapproved														
							FAI	ULT CA	TEGORY					
Landi	ng Ge	ar			_	General	_	,			7	<b></b>	7	
	∐В	Bending				Bend	L	1 '	Program		Outside Dim	ļ	Pressure/Forced	
	Щc	entre No	t Concer	ntric	<u> </u>	BOM/Route		Grain		<u> </u>	Over/Under	tolerance	Set-up	
	$oldsymbol{oldsymbol{ iny}}$	Cracks			Broken/Damage/Defect		Hardwa	are	<u></u>	Part Incorred	<u> </u>	Temperature/Cure		
	Crimp/Kink/Ripple/Wave			Burrs	<u></u>	Inspect	ion Incomplete/Unqua	lified	Part Lost/Mi	ssing	Weld			
	Cuffs					Contamination	<u> </u>	1	tions Incomplete/Uncle	ear	Part Moved	Ĺ	Wrong Stock Pulled	
•	Щc	rushing				Countersink	<u></u>	•	gned/off center		Positioned V	_	<b>-</b>	
	Щн	eat Trea	t	•		Cut Too Short	<u> </u>	Mislab	el <b>ed</b>		Power Loss/	Surge	Other	
	ال	rspection	Strip in	Tube		Drawing		Misrea	d			· · · · · · · · · · · · · · · · · · ·		
,	∟اٍ	/larks/Ch	atter			Drill Holes		Off-set						
	∐т	urning S	equence			Finish		Out of	Calibration					
	Ιlν	Vave/Tw	ist in Tuk	ne .	- 1	Fit/Function		Out of	Sequence					

Work Ord June-12-13 9:2		03086			Page 2						
tem ID: Revision ID: tem Name:	D3443-041 Strut Weldmo	ent Assembly		Accept	*N900040	າ1ດເ	<b>)</b> *	Setup	Start Stop	*NS1* *NS2*	
QC:		Start Qty: 4.00 Req'd Qty: 4.00	*4* *4*		Cust Item ID: Customer:					14( )/	
		an:	Date:	Tooling: SPC (Y/N):	Date:			Run	Start Stop	*NR1* *NR2*	
		START TIM	s as por dwe D3443 IE: 3000 IPERATURE: 4000	Set Up/ Run Hours 0.00 0.00	Tool ID Tool	# Plan Code	Accep Qty	Qt	y ľ	Reject Insp. Number Stamp DA -/-/22 . 34	<b>S</b>
*140 *140* QC Quality Control		QC3- Inspect Part Finish  Memo		0.00   27  9-84 	133		4			*	
150 <b>*150*</b> Small Fab		Smali Fab Memo		0.00			41			14/01/	23 <sup>3</sup> 94

Assemble bearing and ball plungers as per dwg D3443 using DT9518

Ensure bearing rotates smoothly

Small Fab

DQA:		ŧ	Date:												DART
QA Closed:			Date:			WORK ORDER NON	-CC	ONFO	RMANCE / U		Wor	k Order up	odate only	7 .	AEROSPACE
Work Orde	ar.	!				DISPOSITION				AGAINST I	DEP	ARTMENT,	/PROCESS	-1	
WOIK OIGE	-				_	Rework	1		Skid-tube	Crosstube	$\neg$		Water Jet	7	gineering
Part N	Nο					Scrap	1		Machining Machining	Small Fab	$\dashv$	Pro	d. Eng. Coor.	- "	Quality
, aici	-			w		Use-as-is	1 1		noforming	Finishing	$\dashv$		re/Packaging	-	Other
NCR N	No		·			Suspected Unapproved			Large Fab	Composite			Supplier		
Root		i -			Desci	ription of work order update		Initial	Ac	tion	T	Sign &			
Cause		Date	Step	Qty		or non-conformance	Ch	nief Eng	Desc	cription		Date	Verification		QC Inspector
Design		<del>,</del>													
Doc/Data															
Equip/Tooling	Ш											:			
Handling/Pre															
Material															
Operator	Ш												-		
Offset/Setup	Ш														
Process	Ш												:		
Supplier	Ш			•											
Training	Ш														
Transport	Ш														
Unapproved	Ш		ļ												
							FA	ULT CAT	TEGORY						
Landi	ng G	ear			_	General		-		_				_	
	Ш	Bending				Bend		Folio/P	rogram	<u> </u>	$\Box$ <sup>c</sup>	Outside Dim	ensions	Pres	sure/Forced
		Centre No	ot Concer	ntric		BOM/Route		Grain			$\Box$	Over/Under	tolerance	Set-	up
	Щ	Cracks			<u> </u>	Broken/Damage/Defect		Hardwa	re	<u> </u>	F	art Incorre	ct	Tem	perature/Cure
	Ц	Crimp/Kir	ık/Ripple	/Wave		Burrs		Inspect	on Incomplete/L	Inqualified	F	art Lost/Mi	ssing	Wel	d
		Cuffs				Contamination	L	Instruct	ions Incomplete/	/Unclear		art Moved		Wro	ng Stock Pulled
		Crushing				Countersink		Misalig	ned/off center		F	ositioned V	Vrong		
	$\square$	Heat Trea	t			Cut Too Short		Mislabeled				ower Loss/	Oth	er	
	Щ	Inspection	n Strip in	Tube		Drawing		Misread	d		_				
		Marks/Ch	atter			Drill Holes		Off-set			_				
	$\bigsqcup$	Turning S	equence			Finish		Out of 0	Calibration						
	J.  -	Wave/Tw	ist in Tuh	ne .		Fit/Function		Out of	Seguence						

Work Orde June-12-13 9:20		03086		*1030	86*							Page 3
Item ID: Revision ID: Item Name:	D3443-041 Strut Weldme	ent Assembly		Accept 4	<b>N</b> 900	<b>040</b>	100	)*	Setup	Start Stop	1 14	S1*
Start Date: Required Date: Reference:	6/11/13 6/11/13	Start Qty: 4.00 Req'd Qty: 4.00	*4* *4*		Cust Item I Customer:	D:						
Approvals: Process Plan:QC:		Date:	Tooling: SPC (Y/N):	Date:				Run	Start Stop	*N  *N	R1* R2*	
Sequence ID/ Work Center II 160 *160* QC Quality Control	D	Operation Description QC5- Inspect part compl	eteness to step on W/O	Set Up/ Run Hours DAS 0.00 27 0.00 14 1 20	Tool ID	Tool #	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
170 *170* Packaging Packaging		Identify as per dwg & St <b>Memo</b>	ock Location: <u>5T4</u> 8	7 <b>5</b> 0.00 0.00				<u>4</u> x	/ · · · · · · · · · · · · · · · · · · ·	AS 28 / 89	14-01-	-23_

0.00

0.00

180

\*18**0**\*

Quality Control

QC21- Final Inspection - Work Order Release

Memo

MUJ 14-01-24

DQA:	Date:												TRAGE						
QA Closed:		1	Date:			WORK ORDER NON-	·CC	ONFOR	RMANCE / UPDATE	Wo	ork Order up	odate only	AEROSPACE						
		,				DISPOSITION			AGAINST		PARTMENT								
Work Orde	er:				_	——————————————————————————————————————			— Adamsi	—									
						Rework			Skid-tube Crosstube			Water Jet	Engineering						
Part N	10				_	Scrap		1	Machining Small Fab		Pro	d. Eng. Coor.	Quality						
						Use-as-is			noforming Finishing		Rec/Sto	re/Packaging	Other						
NCR N	10	- 1			_	Suspected Unapproved			Large Fab Composite			Supplier							
Root					Descr	iption of work order update		nitial	Action	:	Sign &								
Cause	Da	ate :	Step	Qty		or non-conformance		ief Eng	Description		Date	Verification	QC Inspector						
Design					•				,										
Doc/Data		l																	
Equip/Tooling																			
Handling/Pre						•													
Material																			
Operator																			
Offset/Setup																			
Process																			
Supplier																			
Training																			
Transport						·	İ		·										
Unapproved					<b></b>														
				·		· · · · · · · · · · · · · · · · · · ·	FA	ULT CAT	regory										
Landi	ng Gear				_	General		1			1	سم حسبت	_						
	Bend	-				Bend		1	Program	<u> </u>	Outside Dim	<u> </u>	Pressure/Forced						
		re Not	Concen	ntric	$\vdash$	BOM/Route		Grain		<u> </u>	Over/Under	<u> </u>	Set-up						
	Crac				$\vdash$	Broken/Damage/Defect		Hardwa			Part Incorre	<del>}</del>	Temperature/Cure						
i	_	p/Kink/	'Ripple,	/Wave	<u> </u>	Burrs			ion Incomplete/Unqualified	<u> </u>	Part Lost/Mi	ssing	Weld						
	Cuff					Contamination		4	tions Incomplete/Unclear		Part Moved		Wrong Stock Pulled						
	Crus				<u> </u>	Countersink	lacksquare	1 ~	gned/off center	<u> </u>	Positioned V		<b>7</b> .						
		Treat			$\vdash$	Cut Too Short	$\vdash$	Mislabe			Power Loss/	Surge	Other						
	<b>⊢</b>	ection S		Tube	-	Drawing		Misread			<del></del>		•						
	_	ks/Chat			-	Drill Holes		Off-set				· · · · · · · · · · · · · · · · · · ·							
	<del></del>	ing Seq				Finish Fit/Function	_	4	Calibration										
	i IW/av	e/Twist	ın ilih	10	i i	I FIT / FUNCTION		IDut of 9	Sanuanca										

June-12-13 9:26:43 AM

Work Order ID:

103086

Parent Item:

D3443-041

Parent Item Name:

Strut Weldment Assembly

**Start Date:** 6/11/13

Required Date: 6/11/13


Start Qty: 4.00


Required Qty: 4.00


i arent item itame.	Strat Wordmone 115	oemory .						50	are Qey. 1.00		required	Qiy. 1.00	
Comments:	IPP REV. A 05.11	1.17 NEW ISS	UE	EC									
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3443-1		Manufactured	No			100	Each	20.0000	1	4			14-01-71
Lug									O		· · · · · · · · · · · · · · · · · · ·		110104
		-		<b>Location</b>		Loc Qty	Lo	c Code					14-01-21 13L
				WA002	-	20				15			,
D2442 5			3.1	958	07	20	Б. 1	2 0000		<del>/</del>			
<b>D3443-5</b> Tubing		Manufactured	No			100	Each	3.0000	1	4			14-01-
Luoing				1 42		1 0		6.1			· / · · · · · · · · · · · · · · · · · ·	galagia e e e e e e e e e e e e e e e e e e e	14-01-3
				Location	2025	Loc Oty	Lo	oc Code	(7)	フ			
				WA00 <b>2</b> / O	3035	3			19	<u>'</u>			
				972		2							
D3453-1		Manufactured	No			100	Each	7.0000	1	4			11.6
Clevis									C				14-01
				Location		Loc Qty	Lo	oc Code					JP.
			٠	WA001 1/02	2746	7			_ { _/	<u>/ )</u>			,
				<b>∫</b> 944	72∫	7			13	• •		/	/ D
D3965-4		Manufactured	No			100	Each	11.0000	1	4	14	1/2/	<u> </u>
Bearing, Spherical												101/0	<u> ع کے ع</u>
				<b>Location</b>		Loc Qty	Lo	oc Code			,		
				ST080		11				<del>//</del>			
				893	57	11				<u>/</u>			
D3966-4-750		Manufactured	No			100	Each	44.0000	2	8			14-01
Pin, Dowel													14-01 JB
				<b>Location</b>		Loc Qty	L	oc Code					<i>יוןי</i>
				ST080		12							•
				735	666	12							
				WA002	75	32			<del>\</del>	<u> </u>			
				885	75	32			<u> </u>	5!			


DQA: Date:									_						`AA PT
0 <b>6</b> 'Classada			Data			WORK ORDER NON-	-CC	ONFO	RMANCE / UI	PDATE	147		ا بادد دخوان		AEROSPACE
QA Closed:			Date:								W	ork Order up	date only		
Work Orde	er:					DISPOSITION				AGAINST	DE	PARTMENT	/PROCESS		
	-					Rework			Skid-tube	Crosstube		}	Water Jet		Engineering
Part N	١o.					Scrap		1	Machining	Small Fab		Pro	d. Eng. Coor.		Quality
	•					Use-as-is		Thern	noforming	Finishing		Rec/Stor	re/Packaging		Other
NCR N	No.					Suspected Unapproved			Large Fab	Composite			Supplier		
Root					Doss	ription of work order update		nitial	Act	ion		Cian 9		—	
Cause		Date	Step	Qty	Desci	or non-conformance	1	initial ief Eng		iption		Sign & Date	Verification	n	QC Inspector
Design	$\dashv$	Date	steb	Qty		of non-comormance	Cit	iei Liig	Desci	ιμιιοιι		Date	vermeation		QC mspector
Doc/Data	$\dashv$													į	
Equip/Tooling															
Handling/Pre															
Material		į													
Operator															Б
Offset/Setup															
Process						•									
Supplier															
Training															
Transport															
Unapproved			<u> </u>												
		,					FA	ULT CA	regory						
Landi	ng G	Gear			_	General						-		_	,
	$\vdash$	Bending				Bend		1	Program		L	Outside Dim	ensions	_	Pressure/Forced
	$\vdash$	Centre No	ot Concer	ntric	_	BOM/Route	$oxed{oxed}$	Grain	•	i		Over/Under	tolerance	_	Set-up
	$\vdash$	Cracks			<u> </u>	Broken/Damage/Defect	<u> </u>	Hardwa			<u> </u>	Part Incorred		<u> </u>	Temperature/Cure
	-	Crimp/Kir	nk/Ripple	/Wave		Burrs	<u> </u>		ion Incomplete/Ur	•	_	Part Lost/Mi	ssing	<u> </u>	Weld
	_	Cuffs			_	Contamination	<u> </u>	•	ions Incomplete/U	Inclear	_	Part Moved	l		Wrong Stock Pulled
	$\overline{}$	Crushing			$\vdash$	Countersink	_	1	ned/off center		$\vdash$	Positioned V	- 7	_	l
	$\vdash$	Heat Trea		<b>-</b> .	-	Cut Too Short	<u> </u>	Mislabe			<u>_</u>	Power Loss/	Surge		Other
	-	Inspection	٠.	Tube	$\vdash$	Drawing		Misread							
	$\vdash$	Marks/Ch			-	Drill Holes		Off-set						_	
	$\vdash$	Turning S			$\vdash$	Finish	_	4	Calibration					_	
	L	Wave/Tw	ist in Tub	e		Fit/Function	L	Out of S	Sequence						

H:/FORMS/Quality Assurance\approved QA/NCRWO RevH









ing Landing Magnetic line							ļ		
				•					¥73
							İ		
									:
							İ		:
			·				;	1	*.
								ĺ	- 3
							,		
81								i	
							į		
	44.								
* 1 de		<b>.</b>					ļ		
							!		
							:		
1									
gi ma.						*			
							!		
							!		
									r i
* # * * * *									
		<b>1</b> 1					į		
= 1							;		
					ř				
	e de la composition della comp	ot Ayry S							
•		1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1							